

Oil Field Environmental Incident Summary

Incident: 20151008111531 **Date/Time of Notice:** 10/08/2015 11:15

Responsible Party: DENBURY ONSHORE, LLC

Well Operator: DENBURY ONSHORE, LLC

Well Name: HARR 18 WSW 15

Field Name: SUNSET BUTTE

Well File #: 14265

Date Incident: 10/7/2015 **Time Incident:** 09:35

Facility ID Number:

County: BOWMAN

Twp: 131

Rng: 105

Sec: 18

Qtr:

Location Description: In consturction ditch on new pipeline row 1500 feet south of the CHSU Fed 14-6 WIW

Submitted By: Josh Cuppy

Received By:

Contact Person: Josh Cuppy
5320 LEGACY DR
PLANO, TX 75024-3127

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building: 3.5 Mile

Distance Nearest Water Well: 2 Mile

Type of Incident: Pipeline Leak

Release Contained in Dike: Yes - On Pipeline ROW

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	4	Barrels	4	Barrels	4	barrels

Brine

Other

Description of Other Released Contaminant:

NA

Inspected:

Written Report Received: 10/19/2015

Clean Up Concluded: 10/12/2015

Risk Evaluation:

None

Areal Extent:

Contained in ditch with minimal amount of misting on ROW

Potential Environmental Impacts:

None

Action Taken or Planned:

Shut in well. Released fluids soaked into soil. Recovered soils and sending to LMS Landfill.

Wastes Disposal Location: LMS

Agencies Involved: BLM

Updates

Date: 10/8/2015 **Status:** Awaiting Documentation

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

10/7/2015 at 14:08, on location. Met with site personnel. New injection line is being installed over a 6-mile stretch, and personnel are finding multiple old lines that were not marked or located as they install the line. Old lines appear to be a mix of types. Some are empty, but some still contain fluid. Excavation ditch appears to be catching all fluid released in these events. For this incident, the line was hit just a few hours before the NDDoH inspector arrived to inspect previous line hits related to the injection line project. No cleanup work has yet occurred for the volume released in this incident, as the last line hit is still being cleaned up. However, the released fluid is contained within the bottom of the excavation trench. According to site personnel, the line will be repaired, and impacted soil will be dug out and placed with the soil removed for the previous line hits and sent to disposal in South Dakota. Followup required to check site once cleanup is complete.

Date: 10/8/2015 **Status:** Reviewed - Follow-up Required

Author: Tintes Schiwal, Emily

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Pipeline leak on right of way. Some product misted on soil. Follow-up is necessary.